If this information is required in accessible format, please contact The Regional Municipality of Durham at 1-800-372-1102 ext. 3560.



April 30, 2019

Lisa Trevisan, Director, Central Region Ministry of the Environment, Conservation and Parks Place Nouveau 5775 Yonge Street, Floor 8 North York, ON M2M 4J1

Dear Ms. Trevisan:

RE: Durham York Energy Centre Submission of the 2018 Annual Groundwater and Surface Water Monitoring Report Environmental Compliance Approval 7(14) MECP File #: EA-08-02

In accordance with Condition 7(14) of the Environmental Compliance Approval (ECA), the Regional Municipality of Durham and the Regional Municipality of York (Regions) are pleased to submit the 2018 Annual Groundwater and Surface Water Monitoring Report. Annual monitoring reports are submitted to the Ministry of Environment, Conservation and Parks (MECP) on or before April 30 of each year in accordance with the letter from the MECP Central Region Director to the Regions dated March 4, 2013. This submission will be forwarded to the Energy from Waste Advisory Committee for information in accordance with EA Condition 8.8(b) and posted to the Durham York Energy Centre (DYEC) website in accordance with ECA Condition 7(14)(c).

The 2018 Annual Groundwater and Surface Water Monitoring Report was prepared by an independent and suitably qualified environmental consulting firm, RWDI Air Inc. (RWDI). Based on their review of the monitoring data in 2018, RWDI has concluded that DYEC operations have not had an adverse effect on groundwater quality at the DYEC site. Groundwater analytical results for the required parameters of analysis have consistently satisfied their respective Ontario Drinking Water Standard (ODWS) since monitoring began in 2012, with the exception of elevated chloride and sodium concentrations at Monitoring Well #4 (MW4), which are attributed to deicing salt influence.

The MECP granted permission to suspend surface water monitoring activities during the construction of the Highway 401/Courtice Road interchange via letter dated May 17, 2016. Surface water monitoring in Tooley Creek was not undertaken in 2018 due to ongoing interchange construction.

L. Trevisan, Director, Central Region Submission of the 2018 Annual Groundwater and Surface Water Monitoring Report (MECP File #: EA-08-02) April 30, 2019 Page 2 of 2

We trust that the 2018 Annual Groundwater and Surface Water Monitoring Report meets the expectations of the MECP. If you require any further information, please contact Mr. Gioseph Anello, Manager, Waste Planning and Technical Services, at 905-668-7711 extension 3445.

Sincerely,

Mirka.Januszkiewicz@durham.ca

Mirka Januszkiewicz, P.Eng.Laura McDowell, P.Eng.Director, Waste Management ServicesDirector, Environmental Promotion
and ProtectionThe Regional Municipality of DurhamThe Regional Municipality of York
905-668-4113 extension 3464

c. H. Malcolmson, Director (Acting), Environmental Assessment and Permissions Branch, MECP

Laura.McDowell@york.ca

- A. Cross, Manager, Environmental Assessment Services, MECP
- M. Mahmood, Manager, Approval Services, MECP
- C. Dugas, Manager, York Durham District Office, MECP
- L. Hussain, Manager, Technical Support Section, MECP
- T. Belayneh, Group Leader, Surface Water, MECP
- P. Dunn, Senior Environmental Officer, York Durham District Office, MECP
- P. Martin, Supervisor, Air, Pesticides, and Environmental Planning, MECP
- E. O'Leary, Environmental Resource Planner and EA Coordinator, Air, Pesticides, and Environmental Planning, MECP
- G. Battarino, Project Officer, Project Coordination, MECP
- Energy from Waste Advisory Committee (EFWAC)
- C. Raynor, Regional Clerk, The Regional Municipality of York
- R. Walton, Regional Clerk, The Regional Municipality of Durham